




JOHNEX explosives

MEGAPRIME® Cast Booster

RECOMMENDATION FOR USE



1. When using detonators, begin by inserting the detonator into the larger diameter (cord) tunnel in the red cap at the top of the booster.



4. When using detonating cord, thread the cord fully through both tunnels (starting and finishing at the red capped top) before securing the cord to itself (by knot or tape).



2. Feed the detonator fully through the cord tunnel.



5. Lower charge onto borehole



3. Rotate the detonator 180° and reinsert into the empty detonator capwell.

